MARER PR H9-COSTA

HISTORIC AMERICAN ENGINEERING RECORD

Index to Photographs

Salinas Fortuna Salt Works Intersection of PR Routes 323 & 324 Barrio Costa Municipality of Lajas Puerto Rico HAER No. PR-31

NOTE: These photographs are U.S. Government materials and not subject to copyright. However, the courtesy of a credit line identifying the Historic American Engineering Record and the photographer, Jack Boucher, would be appreciated. All photographs were taken by Jack Boucher in August 1977.

PR-31-1	View of wooden water wheel with sluiceway leading to salt evaporation flats in background.
PR-31-2	Detail view of wooden water wheel possibly used for lifting salt water.
PR-31-3	View of wooden sluiceway leading to salt evaporation flats.
PR-31-4	Detail view of wooden sluiceway.
PR-31-5	View of wood frame shed building and remains of wooden-legged windmill.
PR-31-6	View of wooden-legged windmill with shed building behind.
PR-31-7	View of wooden-legged windmill.
PR-31-8	View of wooden-legged windmill with remnants of cast-iron flywheel crank and pulley in foreground.
PR-31-9	View of main salt-water pumping complex.
PR-31-10	Side view of large, wooden, encased water wheel possibly used for lifting salt-water.
PR-31-11	3/4 view of large, wooden, encased water wheel.
PR-31-12	3/4 view from opposite angle of large, wooden, encased water wheel.
PR-31-13	Detail view of large, wooden, encased water wheel.
PR-31-14	View of wooden sluiceway leading to large, wooden, encased water wheel.

Salinas Fortuna Salt Works HAER No. PR-31 Index to Photographs Page 2

PR-31-15

View of wooden sluiceway leading to salt evaporation ponds.

PR-31-16

n